






Exhibit B
Crosshatch Coating Loss Ratings

Classification	Appearance	Description
5		The edges of the cuts are completely smooth; none of the squares of the cross hatched area are detached.
4		Small flakes of the coating are detached at the intersections of the squares; less than 5% of the total area is affected.
3		Small flakes of the coating are detached along the edges and at intersections of cuts. The area affected is 5 to 15% of the total area.
2		The coating has flaked along the edges and on parts of the squares. The area affected is 15 to 35% of the total area.
1		The coating has flaked along the edges of the cuts in large ribbons and whole squares are detached. The area affected is 35 to 65% of the total area.
0	Greater than 65%	Flaking and detachment worse than classification 1.